


Operating Instructions

Entris

Laboratory Balances





1000038776

User Information

Warning | Danger Symbols used in these Instructions:



These notes identify hazards which have a high probability of resulting in death or serious physical injury if not avoided.



These notes identify hazards that can result in moderate or mild injuries if not avoided.



These notes identify hazards associated with the risk of material damage.

Explanation of Symbols

The following symbols are used in these instructions:

- ▶ Indicates a required action
- Describes what happens after you have performed a particular step

Perform steps in the specified order:

- 1. First action
- 2. Second action
- 3. ...
- Indicates an item in a list

Conventions for this User Manual:

- The illustrations in these instructions are based on "Standard" balances.

Applications Advice | Technical Support

Addresses for applications advice and technical support can be found on the website at: http://www.sartorius.com

Contents

User Information
Contents.
Safety Instructions
Getting Started5
Installation6
Operation
Configuration (Operating Menu) 16 Functions of the Keys during Configuration
Menu Navigation
Application Programs24Counting24Weighing in Percent26Animal Weighing Averaging28Toggling between Weight Units30Density Determination32
Data Interface
Status and Error Messages36
Care and Maintenance37
Recycling
Technical Data
Accessories
EC Declaration of Conformity 46
FCC Supplier's Declaration of Conformity
CSA Certificate of Compliance48

Intended Use

This high-precision balance is designed to be used exclusively indoors under normal atmospheric conditions.

It was developed specifically for the exact determination of the mass of materials in liquid, paste, powder, or solid form. Appropriate containers must be used for each type of sample material.

Safety Instructions

Guidelines and General Information

The balance complies with EU Directives and standards for electrical safety and electromagnetic compatibility*. Improper use or handling can, however, result in damage and or injury.

Any improper use or operation of the balance, i.e., that is not consistent with the instructions, will result in forfeiture of all claims under the manufacturer's warranty.

- Personnel need to have read and understood these installation instructions, including the safety instructions.
- In the event of use in systems and ambient conditions which have greater safety requirements, you must observe the requirements and provisions applicable in your country.
- Always keep the equipment and balance freely accessible. Any installation work or balance operation that does not conform to the instructions

will result in forfeiture of all claims under the manufacturer's warranty.

= see "Specifications"



Danger of Explosion

Do not use this equipment in hazardous areas in which explosive materials are present.



Make sure that the voltage rating printed on the AC adaptor is identical to your local mains voltage.



Installation Instructions Do not operate the device if the

housing or AC adaptor is damaged. Immediately disconnect the damaged device from the power by pulling the plug.

IMPORTANT	Do not expose the balance, its power supply or accessories supplied by Sartorius to extreme temperatures, aggressive chemical vapors, moisture, shock, vibrations or strong electromagnetic fields. Observe the conditions of operation described in the "Technical Data"!
IMPORTANT	Note on Installation: The operator shall be solely responsible for any modifications to the equipment and for connecting an cables or equipment not supplied by Sartorius. Information on operational quality is available upon request from Sartorius. Only use original Sartorius accessories!
	Note the IP protection class of the balance and its power supply! Do not allow liquid penetration. The protection class specifies the suitability of equipment for various environmental conditions (moisture, foreign bodies).
	Before cleaning the AC adapter or the



balance: Unplug the power cord.

The balance may only be opened by specialized personnel trained by Sartorius. Do not open the AC adaptor.



If glass breaks, there is a risk of injury posed by cuts on glass edges.



Lay the cables where they pose no risk of causing someone to trip.

Observe the additional safety and danger information in the following chapters.

Getting Started

Storage and Shipping Conditions

 Do not expose the balance to extreme temperatures, moisture, shocks, blows, or vibration.

Unpacking the Equipment

- After unpacking the device, check it immediately for any external damage.
- If you detect any damage, proceed as directed in the "Care and Maintenance" chapter, "Safety Inspection" section.
- Save all parts of the original packaging for any future transportation. During shipment, please do not leave cables plugged in!

Equipment Supplied

- Balance
- Weighing pan
- Pan support (only for models with a round weighing pan)
- AC adapter with replaceable, countryspecific power plug adapters

Additional equipment on the following models: Entris64-1S, Entris124-1S, Entris224-1S, Entris64i-1S, Entris124i-1S, Entris224i-1S

- Sliding panel draft shield
- Shield disk
- Shield plate
- Dust cover

Additional equipment on the following models:

Entris153-1S, Entris323-1S, Entris423-1S, Entris623-1S, Entris153i-1S, Entris323i-1S, Entris423i-1S, Entris623i-1S

 Round glass draft shield (with shield plate and cover)

Setup


Choose a location that is not subject to the following negative influences:

- Heat (heater or direct sunlight)
- Drafts from open windows and doors
- Extreme vibrations during weighing
- Extreme humidity

Conditioning the Balance

Moisture in the air can condense on cold surfaces whenever the equipment is moved to a substantially warmer place. Allow the device to acclimatize for about 2 hours at room temperature, leaving it unplugged from the power supply.


Installation



Setting up the Balance


Balances with Sliding Panel Draft Shield

- Place the components listed below inside the weighing chamber in the order given:
- Shield plate
- Shield disk
- Pan support
- Weighing pan



Balances with Round Glass Draft Shield

- Position the components listed below in the order given:
- Place lid on top of the balance with the rim facing upwards and rotate until it is securely in place
- Pan support
- Weighing pan
- Glass cover
- Cover with the rim facing downwards



Balances with Round Weighing Pan

- Position the components listed below in the order given:
- Pan support
- Weighing pan

Balances with Rectangular Weighing PanPlace the weighing pan on the balance

AC Power Supply

AC Adapter Assembly



Fatal electric shocks can be caused by use of the incorrect power plug adapter or improper use of the power plug adapter.


- Attach the country-specific power plug adapter to the AC adapter. The power plug adapter must be suitable for the wall outlet at the installation location.
- Do not insert the power plug adapter into the socket without an AC adapter.

ltem number on packaging	Power supply/country-specific power plug adapter (packed in PE bag with printed country code, e.g. EU)	
YEPS01-15VO	Power supply with connection cable	
YEPS01-PS1	USA and Japan (US+JP) Europe (EU) United Kingdom (UK)	
YEPS01-PS2	India (IN) South Africa (ZA) Argentina (AR) Brazil (BR)	
YEPS01-PS3	Australia (AU) Korea (KR) China (CN)	

Select the country-specific power plug adapter. The power plug adapter must be suitable for the wall outlet at the installation location.




- Push the power plug adapter into the AC adapter's holder. The ribbed button must be facing forward.
- Push the power plug adapter all the way in until it audibly engages.
- Check that the power plug adapter is firmly locked in place. To do this, gently pull on the power plug adapter.
- ▷ If the power plug adapter cannot be moved then it is locked in place.



Removing the power plug adapter

- Press on the ribbed button from above and slide the power plug adapter backward.
- Push the power plug adapter out of the AC adapter and remove it.




Connecting the AC Adapter

- Check the voltage rating on the AC adapter's type plate. Make sure that the voltage rating printed on this unit matches the local supply voltage at the place of installation.
- If the stated supply voltage does not comply with the local supply voltage or there is no suitable AC adapter available: Do not use the AC adapter. Contact Sartorius Service.
- Only use original Sartorius AC adapters.
- Connect the angle plug (2) to the power supply socket on the back of the device.
- Connect the power cable (1) to the wall outlet (supply voltage) at the installation location.




Connecting Electronic Peripheral Devices

Make sure that the balance is unplugged from the power supply before connecting | disconnecting a peripheral device (printer or PC) to or from the interface port.



Warm-up Time


In order to provide accurate results, the instrument must warm up for 30 minutes. Only after this time will the required operating temperature have been reached.



Anti-theft Locking Device

To fasten an anti-theft locking device, use the lug located on the back of the balance.

Secure the balance at the place of location, e.g., with a chain or a lock.



Levelling the Balance Purpose:

To compensate for unevenness at the place of installation


Always level the balance again any time after it has been moved to a different location. Only the 2 front feet are used for leveling.


- Screw in both rear support feet (only on models with a rectangular weighing pan).
- ► Turn the front levelingfeet as shown in the illustration until the air bubble is centered within the circle of the level indicator.
- > Normally, several leveling steps are required.
- On models with a rectangular weighing pan: Screw out both back leveling feet until they touch the setup surface.

Underfloor Weighing

A port for a below-cell weighing hook is located on the bottom of the balance.

- ▷ Not permitted for applications in legal metrology.
- Lift cover plate out of the bottom of the balance. Attention: Place the balance on its side, do not turn over completely!
- Secure hook 1: Use a wire, for example, to suspend the sample on the hook.
- ▷ Install a draft shield if necessary.





Operation

19]	1
18		2
	sartorius	
3 Tare Tare R12 CAL II		
16		6
	CF Select Enter	78
14		9
13		10
12		11

Overview of Display and Control Panel

ltem	Description	ltem	Description
1	Weight units	13	Delete (Clear Function)
2	Displays the menu level		This key is generally used to
3	Taring		cancel functions:
4	Symbol for "GLP printing mode active"		 Quit application program Cancel calibration adjustment
5	Symbol for "Printing mode active"		routine Exit menu
6	Application program active	14	Start calibration adjustment
7	Data output:		routine
	Press this key to send readout	15	On Off
	values to the built-in data	16	Symbol: Calibration adjustment
	interface.		function
8	Calculated-value indicator:	17	Symbols for "zero range«
	not a weight value		(verified models only)
9	Start the application program	18	Level indicator
10	Symbol: Gross or net	19	Weight value displayed in selected
11	Select an application program		weight unit
	open the operating menu	Symbol:	
12	Symbols for active application	<<	Exit the operating menu
	(ΔΔ, 🚵, %, 🕰, 🚣, A, C)	<	One menu level higher
		V	Scroll throughmenu items
		>	Next item on current menu level
		_€]	Select a parameter setting

Basic Weighing Function

Features

- Tare the balance
- Printing weights

Preparation

- Switch on the balance: Press the W key
- ► Tare the balance, if necessary: Press the (Tare) key

- If necessary, change the configuration settings: see the chapter entitled "Configuration"
- ▷ If desired, load the factory settings: see the chapter entitled "Configuration"

Additional Functions: ▷ Switching off the balance: Press (10)

Example

Simple Weighing

Step	Press key	Display Printout
1. Switch on the balance Self-test is performed, followed by automatic initial tare function		0.0 g
 Place container on weighing pan (in this example 11.5 g) 		+ 11.5 g
3. Tare the balance		0.0 g
4. Place sample in container (in this example: 132 g)		+ 132.0 g
5. Print weight	Ē	N + 132.0 g

Calibration and Adjustment

Purpose

Calibration is the determination of any difference between the measured value displayed and the true weight (mass) of a sample. Adjustment is the correction of this difference, or its reduction to an allowable level within maximum permissible error limits.

Features

Calibration | adjustment can be performed only when

- there is no load on the balance
- the balance is tared
- the internal signal is stable
- the weight displayed for the sample on the balance must not differ from the nominal weight by more than 2%.

If these conditions are not met, an error message is displayed "ERR D2".

Following calibration | adjustment, the application program is cleared.

Internal Calibration | Adjustment

Note: Only for models with the label Entris...i-1S !

In the operating menu, select *ERL.JUST. - ERL.INT.* before beginning. The built-in motorized calibration weight located in the housing is applied and removed automatically for internal calibration.

- ► Select calibration | adjustment: Press Cal
- > The internal calibration weight is applied automatically
- > The balance is adjusted | calibrated
- > The built-in calibration weight is removed

Internal Calibration | Adjustment

Note: Only for models with the label **Entris..i-1S** ! Set the following parameters: SETUP - BAL.SEAL.- EAL.JUST.- EAL.INT. (Code 1.1.9.4)

The built-in motorized calibration weight located in the balance housing is applied and removed automatically for internal calibration.

	Step	Key (or instruction)	Display
1.	Tare the balance	Tare	0.0 g
2.	Start calibration	Cal	CAL.INT.
	The internal calibration weight is applied automatically		CAL.RUN.
3.	Adjustment carried out		CAL.END
4.	The internal weight is defined automatically		0.0 g

External Calibration

Set the following parameters: SETUP - BAL.SEAL.- EAL.JUST. - EAL.EXT. (Code 1.1.9.1) The required calibration weight is configured at the factory (see "Specifications").

Step	Key (or instruction)	Display
1. Tare balance	Tare	0.0 g
2. Start adjustment routine	Cal	CAL.EXT.
Once you store the zero point the display prompts for the required calibration weight (flashing display)		<pre><- 5000.0 g</pre>
 Apply the prompted calibration weight (in this example 5000 g). Weight too low: a minus sign "-" is shown Weight too high: a plus sign "+" is shown 		5000.0 g
The display stops flashing as soon as the weight value is within the defined limit.		
4. Calibration/adjustment executed;		EAL.EN]
then the calibration weight is displayed		+ 5000.0 g
5. Remove the calibration weight		0.0 g

Configuration (Operating Menu)

You can configure the balance; i.e., adapt it to individual requirements.

Functions of the Keys during Configuration:

Symbol	Кеу	Function
V	Select Menu	Scroll through menu items
>	Enter	One menu level lower (use right cursor to scroll through up to 4 menu levels)
é.	Enter	Confirm menu item
	CF (Press and hold)	Save settings and exit menu from any position
<<	CF	At the top level: Save settings and exit menu:
<	CF	One menu level higher (left cursor)
[••••]		Indicates menu level

Menu Navigation Example: Setting the Language


Step	Key (or instruction)	Display
 Open the menu: Open the menu in weighing mode 	Select hold	APPLIC.
 Scroll upward within themenu level; After the last menu code, the first code is displayed again 	Repeatedly	INPUT LANGUAG.
 Select the next menu level (scrolls to the right) 	Repeatedly	ENGLISH °
5. Change setting: Scroll until the desired setting is shown	Seket	GERMAN
6. Confirm the menu code ; "o" indicates the active setting	Enter	GERMAN °
 7. Return to the next higher menu level ▷ Set other menu items as desired 	CF Select Menu, Enter	LANGUAG.
8. Save settings and exit menu	Repeatedly:	Constant + Consta
or		
Exit menu without saving changes		
> Restart your application		0.0 g

Level 1 [•] Level 2 [••] Level 3 [•••] Menu code AMBIENT conditions APP.FILT. Application filter T BALISCAL. SETUP ------1.1.1. 1. 1. 2. Balance | scale parameters STAB.RNG.Stability range 1.1.3. STHURING Taring 1) 1.1.5 - RUTZER, Auto zero 1.1.6 WT.UNIT Basic weight unit 1. 1. 7. - DISPLAY Display accuracy 1.1.8. EAL./ADJ. Function of the Cal key 1. 1. 9. ERELINIT. weight unit for calibration IRUITATE PARITY Parity 1.1.11 INTERF. Interface 1.5.1. 1.5.2. — STOPBIT Number of stop bits 1.5.3. HANDSHK. Handshake mode 1.5.4 DATABIT Number of data bits 1. 5. 5. DRT.REE. Output: SBI (ASCII) or printout 1. 5. 6. PRIMI (manual | automatic) 1.6.2. STOPRUT. Stop automatic printing 1.6.2. MUTLYEL. Time-dependent autom. printing 1.6.3. TBR./PRI. Tare bal./balance after ind. print 1.6.5. PRT.INIT. Printout of appl. parameters 1.6.5. COMPLET line format for printout 1.6.6. - PRINT (manual | automatic) 1. 6. 1. PRNT.DUT Settings for print function - FORMAT Line format for printout MENU Menu read only | can edit 1.8.1. - EXTRAS - SIGNAL Acoustic signal (beep) KEYS (Keypad) (Additional functions) 1.8.2. 1.8.3. - EXTREY External switch function 1.8.4. - ONMODE Power-on mode 1.8.5. BACKLIT Display backlighting 1.8.6 - MENU Factory settings - RESET -1.9.1. APPLIC.ation - WEIGH 2.1. programs 2.2.2. 2.3.1. REF.UPIT. Autom. ref. sample updating 2.3.2. PERCENT Weighing in percent ______ BEC.PLCS Decimal places 2 4 1 - ANIMALW.eighing — ACTIVITY. Animal activity 2.7.1. START 2.7.2. — METHOD (Operator) - CALC.ulation ——— 2.8.1. ELEPTICS Decimal places JELPLCS Decimal places JELPLCS Decimal places 2.8.2. 2.9.1. _____ ID input; max. 7 characters, e.g. as 3. 1. INPUT Input ____ IDNO. _____ Inventory no. INFOrmation — VERSION, SER, NO., MODEL — — Display software ver., serial no., model 4. 1. .2. .3. LANGUAG - ENGLISH (factory setting) 5.1. TEUTSEH (German) (LANGUAG.) 5.2 - FRANE cais (French) 5.3. ITAL.iano (Italian) 5.4. ESPANOL (Spanish) 5.5. РҮССКИИ (Russian) 5.6. POLSKI (Polish) 5.7. EDJES Menu shows codes (not texts) 5.8.


Parameter Settings (Overview)

Parameter Settings (Overview) o = Factory setting; $\sqrt{}$ = User-defined setting

Level 1	Level 2	Level 3	Level 4	Menu code
SETUP	BAL.SEAL. Balance parameters	AMBIENT o conditions o (Filter adaptation)	VERY STAÐLE STAÐLE UNSTAÐL VERY UNSTAÐLE	1. 1. 1. 1 1. 1. 1. 2 1. 1. 1. 3 1. 1. 1. 4
	-	— APP.FILT o Application filter		1. 1. 2. 1 1. 1. 2. 2
	_		<pre>I/4 DI5. (digit) I/2 DI6. (digit) I - DI6IT (digit) 2 - DI6IT (digit) 4 - DI6IT (digit) 8 - DI6IT (digit)</pre>	1. 1. 3. 1 1. 1. 3. 2 1. 1. 3. 3 1. 1. 3. 4 1. 1. 3. 5 1. 1. 3. 6
	-	TARING Taringo	₩/᠐도T분(W o stability) ₩/도TAB(After stability)	1. 1. 5. 1 1. 1. 5. 2
	-	AUT.ZERO o	OFF ON	1. 1. 6. 1 1. 1. 6. 2
	-	WT.UNIT Basic weight through unit	For list of units, see Chapter Toggling between weight units"	1. 1. 7. 1 1. 1. 7.23
	-	Display o	ALL MINUS I DIVIS. I 1 interval	1. 1. 8. 1 1. 1. 8. 2 1. 1. 8. 6
	-	EAL./A]]J. Function of the o of the Cal	EAL.EXT.External cal. adj. EAL.INT Internal cal. adj. KEY BLOEKED (a) blocked	1. 1. 9. 1 1. 1. 9. 2 1. 1. 3. 3
		EAL.UNIT Unit o for calibration weight	GRAMS KILOGR.ams POUNIS	1. 1.11. 1 1. 1.11. 2 1. 1.11. 3



Level 1	Level 2	Level 3	Level 4 [●●●●]	Menu code
SETUP	PRNT.OUT Printing fct.	PRT.INIT. Printing applica- o tion parameters	OFF RLL parameters MRINPAR.ameters	1. 6. 5. 1 1. 6. 5. 2 1. 6. 5. 2
		FORMAT Line for o	፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡፡	1. 6. 6. 1 1. 6. 6. 2
	EXTRAS (Additional functions)	MENU	EANEDIT.le RD.ONLY read only	1. 8. 1. 1 1. 8. 1. 2
		SIGNAL o	OFF ON	1. 8. 2. 1 1. 8. 2. 2
		KEYS o (keypad)	FREE LOCKED	1. 8. 3. 1 1. 8. 3. 2
		EXT.KEY o External switch function	PRINT Key / Z TRRE Key Tare ERL. Key Cal SELEET Key Cr EF Key Cr ENTER Key Enter	1. 8. 4. 1 1. 8. 4. 2 1. 8. 4. 3 1. 8. 4. 4 1. 8. 4. 5 1. 8. 4. 6
		ON-MODE o Power-on mode	DFF/DN Off on stand-by STANJBY On Stand-by AUTO-DN Automatic on mode	1. 8. 5. 1 1. 8. 5. 2 1. 8. 5. 3
		BACKLII o Display o backlighting	OFF DN	1. 8. 6. 1 1. 8. 6. 2
	- RESET Menu reset	MENU o	YES restore factory settings NO Do not restore factory settings	1. 9. 1. 1 1. 9. 1. 2



Level 1		Level 2	Level 3	Example	Code
INFO		VER.NO.	 Show software version	REL.32.09	4. 1.
rmation		SER.NR.	 Show serial number, e.g.: (To toggle focus between upper and lower display sections: Press (Select Mem.)	297 12345	4. 2.
	M	MODEL	 Show model designation (to change focus from upper to middle to lower display section and back: Press (Select)	ENTRIS 124- 19	4.3.

Device-Specific Information

Display of Menu Items: Selecting Languages or Codes

ENGLISH (factory setting)	5.1.
וווידענא (German)	5.2.
FRANE.çais (French)	5.3.
ITAL.iano (Italian)	5.4.
ESPANOL (Spanish)	5. 5.
PYEEK (Russian)	5. 6.
POLSKI (Polish)	5.7.
CODES Menu shows codes (not texts)	5.8.
	ENGLISH (factory setting) DEUTSCH (German) FRANC.çais (French) ITAL.iano (Italian) ESPANDL (Spanish) PYECK (Russian) POLSKI (Polish) EDDES Menu shows codes (not texts)

Application Programs

Counting

Display symbol: 👬

Purpose

With the Counting application, you can determine the number of parts that each have approximately equal weight. To do this, a known number of parts (the reference sample quantity) is weighed first, and the individual piece weight (reference weight) is calculated from this result. Thus the number of parts subsequently placed on the balance can be determined from their weight.

Changing the Reference Sample Quantity

Activate function: Press the key Select the desired reference sample quantity (1 to 100): In increments of 1: Press the key briefly In increments of 10: Press and hold the key. The quantity is stored in battery-backed

memory.

Reference Sample Updating

Automatic reference sample updating optimizes the counting accuracy. You can activate or deactivate this function in the menu.


Automatic reference sample updating is performed when the requirements, including the specified stability criterion, have been met.

The abbreviation $\square \square \square \top$ for "optimizing", is displayed briefly with the new reference sample quantity.

Preparation

- Select the Counting application in the menu: see "Configuration"
- ▶ Set the following parameters:

APPLIE.ation programs



o = Factory setting

Printout: Counting

			J	
nRef		10		: Ref. sample quantity
wRef		21.14	g	: Reference weight
				for 1 unit
Qnt	+	500	pcs	: Calculated quantity

Example: Counting parts of equal weight Parameter settings: RPPLIC. - COUNT. (menu code 2. 3.)

Step	Key (or instruction)	Display Data output
1. Place empty container on the balance		+ 22.6 g
2. Tare the balance	Tare	0.0 g
3. Add reference sample quantity to container (in this example: 20 pcs)		
4. Changing the reference sample quar	ntity	Select REF IDpcs
5. Select reference sample quantity: In increments of 1 (1, 2, 3,, 100) In increments of 10 (10, 20,, 100)	Repeatedly: <u>Heter</u> Press briefly <u>Heter</u> press and hold	REF 20pcs
6. Confirm selected reference sample quantity and start the application. The current reference weight remains saved until a new reference is set or the power supply is interrupted	Enter	+ 2∏pcs * nRef 20pcs wRef 1.07g
7. Add desired number of pieces		+ 500pcs
8. If desired, print quantity	Ē	Qnt + 500 pcs
9. Toggle display between mean piece weight, weight, quantity	Repeatedly: Select	+ 1.07g&* + 535.0g * + 500pcs *
 10. Unload the balance 11. Repeat as needed, starting from Step 	◆ ↑ 0 7	- 2'¦pcs *
12. End "Counting"	CF	0.0 g

Weighing in Percent

Display symbol: %

Purpose

This application allows you to obtain weight readouts in percent which are in proportion to a reference weight.

Changing the Reference Percentage

Activate function: Press the Select Meru key

Select the desired reference (1 to 100): In increments of 1: Press the key briefly

Increments of 10: Press and hold the $\frac{\text{Select}}{\text{Mem}}$ key.

The percentage is stored in batterybacked memory.

Preparation

- Select the Weighing in percent application in the menu: see "Configuration"
- ▶ Set the following parameters:

APPLIE.ation programs

— PERCENT Weighing in percent

- NONE Decimal places
- o IDEE.PL. 1 decimal place
- 2 IEC.PL. 2 decimal places
- \exists $\mathbb{IEE.PL.$ 3 decimal places

o = Factory setting

Printout: Weighing in percent

pRef	100	: Reference percentage
Wxx%	111.6 g	: Reference weight for
		selected reference
		percentage xx%
Prc	+ 94.9 %	: Calculated reference
		percentage

Example: Determining residual weight in percent Parameter settings: *RPPLIE*. - *PEREENT* (menu code 2. 4.) Reference percentage: *REF* 100%

Ste	р	Key (or instruction)	Display Data output		
1.	Tare the balance	Tare		0.0 g	1
2.	Changing the reference: (see the previous page)	Select Menu	REF	100 %	3
3.	Place sample equal to 100% on the balance (in this example: 111.6 g)				
4.	Start the application. The current reference weight remains stored until a new reference is set or power to the power supply is interrupted	Enter	+ pRef Wxx%		* 100 % 111.6 g
5.	Remove sample (e.g. for drying)				
6.	Place weight on the balance (in this example 322.5 g)		+	94.9 %	[%] *
7.	If desired, print percentage	I	Prc	+	94.9 %
8.	Toggle display between weight and percentage	Repeatedly: Select	+ +	105.9 94.9 %	
9.	Clear display of residual weight and reference percentage Exit application	CF	+	105.9 ç	J
10.	If desired, print net residual weight	I	N	+	105.9 g

Animal Weighing | Averaging

Display symbol: 🕰

Purpose

This application is used to determine the weights of unstable samples (e.g., live animals) or to determine weights under very unstable ambient conditions. With this program, the balance calculates the weight as the average of a defined number of individual weighing operations (also referred to as "subweighing operations").

Changing the Number of Subweighing Operations

Activate function: Press the key Select the desired number of measurements (1 to 100): In increments of 1: Press the key briefly Increments of 10: Press and hold the key.

The selected number of measurements is stored in battery-backed memory.

Preparation

- Select the Animal weighing application in the menu: see "Configuration"
- ► Set the following parameters:

 APPLIC.ation programs

 ANIMALW. Animal weighing

 RETIVTY. Animal activity

 CALM Stable readout

 O

 RETIVE Unstable

 V.ACTIVE Very unstable

 START

 O

 ANUAL

 O

 AUTOM.atic

o = Factory setting

Printout: Animal weighing

mDef 20 :Numbe	er of
subwe	ighing
operat	ions
x-Net + 410.1 g : Calcula	ated average

Example: Determining animal weight with automatic start and 20 subweighing operations (measurements)

Parameter settings: APPLIE. - ANIMALW. (menu code 2. 7.)

Step	Key (or instruction)	Display Data output
1. Place animal weighing bowl on the balance		22.6 g
2. Tare the balance	Tare	0.0 g
3. Change the number of subweighing operations:	Select Menu	REF 30
4. Select number of measurements: In increments of 1 (1, 2, 3,, 100) In increments of 10 (10, 20,, 100)	Repeatedly: Select Press briefly Select press and hold	REF 20
5. Confirm number of measurements and start automatic animal weighing. The number of measurements remains stored in battery-backed memory until the setting is changed	Enter	+ 0.0g _*
6. Place first animal in bowl. The balance delays the start of measurements until the difference between 2 measure- ments meets the criterion		888 19 20
7. Read off the result. The result is displayed with		+ Ч![].¦g _{▲*}
the "*" symbol (= calculated value) and remains displayed until the sample (animal) is removed from the load plate (bowl)	_	mDef 20 x-Net + 410.1 g
8. Unload the balance		+ 0.0g *
9. Weigh next animal (if des.)		

Next weighing series begins automatically

Toggling between Weight Units

Purpose

With this application program you can change the weight value displayed from the basic weight unit to any of 4 application weight units (see table on next page).

Features

- Set the basic unit and display accuracy in the Setup menu: see "Configuration".
- Set the application weight units and display accuracies in the Application menu.
- These settings are stored in battery-backed memory.
- The basic unit is active when the balance is powered up.

Example: Change display from the basic unit (in this example, grams [g]) to pounds [lb] and Troy ounces [ozt].

Set the following parameters: **APPLIC.** - UNIT (code 2. 2.)

Step	Press key	Display Printout
Preparation:		
 Begin selection of an application weight unit 	Select Menu	NONE º [•]
 Select an application unit, in this example "pounds" (see table on next page) 	Repeatedly:	POUNIIS
3. Confirm the weight unit (pounds)	Enter	POUNJE o
4. Select the next application weight	Enter,	NONE º [••]
unit, in this example: Troy ounces (see table on next page)	Repeatedly:	TROY.OZ.
5. Confirm weight unit (Troy ounces)	Enter	TROY.02. º
6. Select other application units if desire (otherwise, confirm "№" by pressing ([••••]
7. Store selection	CF	0.00 g
Conversion: 8. Place sample on balance	☆ 	+ 100.00 g
9. Toggle unit for weight value	Repeatedly:	+ 0.22046 lb + 3.5275 ozt

Depending on the country-specific model version, not all weight units listed may be available.

Menu item	Unit	Conversion factor	Display symbol
1) USERDEF.	Grams	1.0000000000	0
2) GRAMS (Factory setting)	Grams	1.0000000000	g
3) KILOGR.	Kilograms	0.0010000000	kg
4) CARATS	Carats	5,0000000000	0
5) POUNDS	Pounds	0.00220462260	lb
6) DUNCES	Ounces	0.03527396200	OZ
7) TROY.02.	Troy ounces	0.03215074700	ozt
8) HKTAEL	Hong Kong taels	0.02671725000	tl
9) SING.TAEL.	Singapore taels	0.02645544638	tl
10) TWN.TREL.	Taiwanese taels	0.02666666000	tl
11) GRAINS	Grains	15.4323583500	GN
12) PENY.WT.	Pennyweights	0.64301493100	dwt
13) MILLIGR.	Milligrams	1000.00000000	mg
14) PT.P.L B.	Parts per pound	1.12876677120	0
15) EHINA.TAEL	Chinese taels	0.02645547175	tl
16) MOMMES	Mommes	0.26670000000	m
17) AUST.CT.	Austrian carats	5.0000000000	Kt
18) TOLA	Tola	0.08573333810	0
19) BAHT	Baht	0.06578947436	b
20) MESGHAL	Mesghal	0.21700000000	0
21) TONS	Tons	0.00000100000	t
22)LI/0Z1)	Pounds : ounces	0.03527396200	lb oz
23) NEWTON	Newton	0.00980665000	Ν

¹) = The format for display of pounds: ounces is xx:yy.yyy; x=lb, y=oz

Density Determination

Display symbol: ₫Ճ

Purpose

This application program lets you determine the density of solid substances using the buoyancy method.

Features

To enter the density of the buoyancy liquid(g/cm³) at the corresponding temperature, press $\frac{1}{2}$. See the next page for a table of density values for water. The factory setting is 1 g/cm³.

The following formula is applied:

Density of sample =

Weight in air

----- + density of liquid

(Weight in air – weight in water)

When you start the density determination routine, the density of the liquid is displayed briefly.

Positive and negative values can be stored for weight in air and weight in water. The weight in water must be less than the weight in air; otherwise, an error message is displayed.

The results can be displayed with 0 to 3 decimal places: see "Configuration". Not part of the scope of delivery: sample holder and suspension wire.

Note on using 3 decimal places.

Preparation

Select the Density Determination application in the menu: see "Configuration"

	note on using 5 decimal placest		
Set the following parameters:	Using three decimal places for		
APPLIC. ation programs	density can result in a high measurement error rate because		
DENSITY determination	corrections to the air density and		
DEC.PLES Decimal places	the density calculation sets are not taken into account, for example.		
NONE No decimal places			

0 / 200. 0.	i acciniai piace
2 DEC.PL.	2 decimal places
∃ DEC.PL.	3 decimal places

o = Factory setting

Printout for Density Determination

RhoFl 0.99823 o	: Density of liquid (g/cm ³)
Wa + 20.0 g	: Weight in air
Wfl + 15.0 g	: Weight in liquid
Rho 4.0 o	: Result: density of the sample
	· ··· · · · · · · · · · · · · · · · ·

Table: Density of H_2O at Temperature T (in °C)

T/°C	0.0	0.1	0.2	0.3	0.4	0.5	0.6	0.7	0.8	0.9
10.	0.99973	0.99972	0.99971	0.99970	0.99969	0.99968	0.99967	0.99966	0.99965	0.99964
11.	0.99963	0.99962	0.99961	0.99960	0.99959	0.99958	0.99957	0.99956	0.99955	0.99954
12.	0.99953	0.99951	0.99950	0.99949	0.99948	0.99947	0.99946	0.99944	0.99943	0.99942
13.	0.99941	0.99939	0.99938	0.99937	0.99935	0.99934	0.99933	0.99931	0.99930	0.99929
14.	0.99927	0.99926	0.99924	0.99923	0.99922	0.99920	0.99919	0.99917	0.99916	0.99914
15.	0.99913	0.99911	0.99910	0.99908	0.99907	0.99905	0.99904	0.99902	0.99900	0.99899
16.	0.99897	0.99896	0.99894	0.99892	0.99891	0.99889	0.99887	0.99885	0.99884	0.99882
17.	0.99880	0.99879	0.99877	0.99875	0.99873	0.99871	0.99870	0.99868	0.99866	0.99864
18.	0.99862	0.99860	0.99859	0.99857	0.99855	0.99853	0.99851	0.99849	0.99847	0.99845
19.	0.99843	0.99841	0.99839	0.99837	0.99835	0.99833	0.99831	0.99829	0.99827	0.99825
20.	0.99823	0.99821	0.99819	0.99817	0.99815	0.99813	0.99811	0.99808	0.99806	0.99804
21.	0.99802	0.99800	0.99798	0.99795	0.99793	0.99791	0.99789	0.99786	0.99784	0.99782
22.	0.99780	0.99777	0.99775	0.99773	0.99771	0.99768	0.99766	0.99764	0.99761	0.99759
23.	0.99756	0.99754	0.99752	0.99749	0.99747	0.99744	0.99742	0.99740	0.99737	0.99735
24.	0.99732	0.99730	0.99727	0.99725	0.99722	0.99720	0.99717	0.99715	0.99712	0.99710
25.	0.99707	0.99704	0.99702	0.99699	0.99697	0.99694	0.99691	0.99689	0.99686	0.99684
26.	0.99681	0.99678	0.99676	0.99673	0.99670	0.99668	0.99665	0.99662	0.99659	0.99657
27.	0.99654	0.99651	0.99648	0.99646	0.99643	0.99640	0.99637	0.99634	0.99632	0.99629
28.	0.99626	0.99623	0.99620	0.99617	0.99614	0.99612	0.99609	0.99606	0.99603	0.99600
29.	0.99597	0.99594	0.99591	0.99588	0.99585	0.99582	0.99579	0.99576	0.99573	0.99570
30.	0.99567	0.99564	0.99561	0.99558	0.99555	0.99552	0.99549	0.99546	0.99543	0.99540

Parameter settings: APPLIC. - DENSITY - DEC.PLCS. - I DEC.PL. (menu code 2. 9. 1. 2)

Example: Determining the density of a solid using water as the buoyancy liquid. The density of water at 20°C is 0.99823 g/cm^3 .

Step	The density of water at 20°C is (Key (or instruction)	Display Data output
1.	Attach sample holder and suspension	wire	
2.	Tare the balance	Tare	0.0 g
3.	Edit the stored density value	Select Menu	_ 1.00000
4.	Enter the density of the liquid (in this example: 0.99823)	Repeatedly: Select, briefly or press and hold ; Enter, etc.	_0.99823
5.	Save density value and start application. The density value is stored in battery-backed memory until the setting is changed	Enter	
6.	Confirm "뭐IR" display	Enter	AIR ?
7.	Determine the weight of sample in the air: Place sample on the balance		+ 20.0 g _{?*}
8.	Store value for weight in air	Enter	
9.	Remove sample from the balance		WATER ?
10.	Determine weight in liquid: Place sample in holder		
11.	Confirm "WATER" display	Enter	0.0 g _{?*}
12.	Immerse sample in liquid		+ /5.0 g _{?*}
13.	Store value for weight in liquid, view and print result	Enter	+ 4.0°;*
			RhoFl 0.6237 o Wa + 20.0 g Wfl + 15.0 g
14.	Delete result	CF	Rho 4.0 o
1 5	Demost as used all starting from Chan	F	


15. Repeat as needed, starting from Step 5

Data Interface

Purpose

Your balance comes equipped with an interface port for connection to a computer or other peripheral device. You can use an on-line computer to change, start and/or monitor the functions of the balance and the application programs.

Female interface connector



Pin Assignment Chart, 25-pin, RS-232:

- Pin 1: Shield Pin 2: Data output (TxD) Pin 3: Data input (RxD)
- Pin 4: Internal ground (GND)
- Pin 5: Clear to Send (CTS)
- Pin 6: Not connected
- Pin 7: Internal ground (GND)
- Pin 8: Internal ground (GND)
- Pin 9: Not connected
- Pin 10: Not assigned
- Pin IO: Not assigned
- Pin 11: + 12 V (operating voltage for Sartorius printer)
- Pin 12: Reset _ Out
- Pin 13: + 5 V
- Pin 14: Internal ground (GND)
- Pin 15: Universal remote switch
- Pin 16: Not connected -
- Pin 17: Not connected
- Pin 18: Not connected
- Pin 19: Not connected
- Pin 20: Data Terminal Ready (DTR)
- Pin 21: Not connected
- Pin 22: Not connected
- Pin 23: Not connected
- Pin 24: Not connected
- Pin 25: + 5 V

*) = Hardware restart

Preparation

You can set these parameters for other devices in the Setup menu: see "Configuration".

You will also find a detailed description

of the available data interface commands in the file "Data Interface Descriptions for Entris Models", which you can download from the Sartorius website: (www.sartorius.com "Download Center".)

For remote switch*)

Status and Error Messages

Error codes are shown on the main display for approx. 2 seconds. The program then returns automatically to the previous mode.

Display	Cause	Solution
No segments appear on the display	No AC power is available The power supply is not plugged in	Check the AC power supply Plug in the power supply
HIGH	The load exceeds the balance capacity	Unload the balance
LOW or ERR 54	Something is touching the weighing pan	Move the object that is touching the weighing pan
RPP.ERR.	Cannot store data: Load on weighing pan too light or no sample on pan while application is active	Increase load
DIS.ERR.	Display error: Data output not compatible with output format	Change the configuration in the operating menu
PRT.ERR.	Interface port for printer output is blocked	Reset the menu factory settings or Contact your local Sartorius Service Center
ERR D2	Calibration parameter not met, e.g.: – Press (Tare) to tare the balance – load on weighing pan	Calibrate only when zero is displayed Unload the balance
ERR ID	The (Tare) key is blocked for active application programs; Only 1 tare function can be used at a time	After the tare memory has been deleted using the \bigcirc key, the \bigcirc key can be used again
ERR II	Tara memory not allowed	Press Tare
The weight readout changes constantly	Unstable ambient conditions (excessive vibration or draft) A foreign object is caught between weighing pan and housing	Set up balance in another area Adjust Setup configuration Remove the foreign object
The weight readout is obviously wrong	The balance was not calibrated/adjusted Balance not tared before weighing	Calibrated adjust the balance

If any other errors occur, contact your local Sartorius Service Center.

Contact information: http://www.sartorius.com

Care and Maintenance

Service

On request, Sartorius can offer you an individual service contract.

Repairs

Repair work must only be carried out by trained service technicians. Repairs performed by untrained persons may result in considerable hazards for the user.

Cleaning




Unplug the AC adapter from the wall outlet (mains supply). If you have an interface cable connected to the balance port, unplug it from the port. Make sure that no liquid enters the balance housing.

- ► Clean the balance with a cloth lightly moistened with soap solution.
- ▶ The plastic top and bottom parts of the balance housing have a special coating that allows acetone to be used to clean these parts.



Do not clean the following parts with acetone or aggressive cleaning agents: foil-covered keypad, power connector port, data interface, or any other plastic parts.

▶ Wipe the balance with a soft, dry cloth.



On analytical balances remove and clean the weighing pan as follows:



Reach beneath the shield disk and lift it up carefully together with the weighing pan to avoid damaging the weighing system.

Make sure that no liquid enters the balance housing.

Cleaning Stainless Steel Surfaces

Clean all stainless steel parts regularly. Remove the stainless steel weighing pan and thoroughly clean it separately. Use a damp cloth or sponge to clean stainless steel parts on the balance.

You can use any household cleaning agent that is suitable for use on stainless steel. Clean stainless steel surfaces only by wiping them down. Then rinse the equipment thoroughly, making sure to remove all residues.

Afterwards, allow the equipment to dry. If desired, you can apply oil to the cleaned surfaces as additional protection.

Recycling

Safety Inspections

If there is any indication that safe operation of the balance is no longer warranted:

- Disconnect the equipment from the AC power: Unplug the power cord.
- > Lock the balance in a secure place to ensure that it cannot be used for the time being.

Recycling

The packaging is made of environmentally friendly materials that can be used as secondary raw materials. If you no longer need this packaging, bring it to your local recycling and waste disposal facility according to the regulations applicable in your country.

(Contract number D-59101-2009-1129). Otherwise you should dispose of the material in accordance with the waste disposal regulations that are applicable in your area.



The equipment, including accessories and batteries, does not belong in your regular household waste. The EU legislation requires its Member States to collect electrical and

electronic equipment and disposed of it separately from other unsorted municipal waste with the aim of recycling it. For more information regarding disposal and recycling, please contact our local service representatives. Our partners listed on the following website will also be able to provide assistance within the EU:

- 1) Go to http://www.sartorius.com.
- 2) Select the "Services" tab.
- 3) Then select "Disposal Information".
- Addresses for the local Sartorius disposal contacts can be found in the PDF files available for download on this page.

	6	

Sartorius will not take back equipment contaminated with hazardous materials (ABC contamination) – either for repair or disposal.

Service address disposal:

Please refer to our website (www.sartorius. com) or contact the Sartorius Service Center for more detailed information regarding repair service addresses or the disposal of your device.

Technical Data

General Specifications

	Unit	Value
Int. weight circuit		
All models with the designation Entris i-1S are equipped with an internal calibration weight.		
Power consumption (including AC adapter)		
Maximum	VA	16
Typical	VA	8
Operating time with external battery YRB11Z (display backlighting on), approx.	h	35
Supply voltage		
Only via Sartorius AC adapter YEPS01-15VO with country-specific power plug adapters (for country-specific power plug adapters see chapter "Installation")		
Electromagnetic Compatibility (EMC) as per EN61326-1:		
Transient emissions: Class B		
Defined immunity to interference: Industrial areas		

Ambient Conditions

	Unit	Value
Temperature		
Storage and transport	°C	+10 to +40
Operation	°C	+10 to +40

AC adapter

	Unit	Value
Power supply (primary)		
Voltage	V _{AC}	100-240 ±10%
Current	A	0.2
Frequency	Hz	50-60 ±5%
Power supply (secondary)		
At between 0°C and +40°C	V_{DC} mA (max.) W (max.)	15 ±5 % 530 8
At between +40°C and +50°C	V_{DC} mA (max.) W (max.)	15 ±5 % 330 5
Installation location, above sea level (NN)	m	3000
Protection class according to EN/IEC 60950-1		11
Protection class according to EN/IEC 60529		1P40
Dimensions (L×W×H)	mm	$100 \times 60 \times 50$
Weight	g	90,0

Model-specific Specifications

Modele: Entris		224-1x ¹⁾ 224i-1x ¹⁾	124-1x ¹⁾ 124i-1x ¹⁾	64-1x ¹⁾ 64i-1x ¹⁾
Weighing capacity	g	220	120	60
Readability	g	0.0001	0.0001	0.0001
Tare range (subtractive)	g	220	120	60
Repeatability (standard deviation)	< ± g	0.0001	0.0001	0.0001
Linearity deviation	< ± g	0.0002	0.0002	0.0002
Typical stabilization time	S	2.5	2.5	2.5
Sensitivity drift within +10°C +30°C	< ± ppm/K	3	3	3
Adaptation to ambient conditions		By selection or display update	f 1 of 4 optimiz :: 0.1–0.4 (depe	ed filter levels; nds on filter level selected)
External calibration weight (of at least accuracy class)	g	200 (E2)	100 (E2)	50 (E2)
Net weight, approx.	kg	4.4 4.8	4.4 4.8	4.4 4.8
Weighing pan size	mm	Ø 90	Ø 90	Ø 90
Weighing chamber height*	mm	230	230	230
Dimensions ($W \times D \times H$)	mm	230 × 303 × 33	0	
Modele: Entris		623-1x ¹⁾ 623i-1x ¹⁾	423-1x ¹⁾ 423i-1x ¹⁾	323-1x ¹⁾ 323i-1x ¹⁾
Modele: Entris Weighing capacity	g			
	g	623i-1x ¹⁾	423i-1x ¹⁾	323i-1x ¹⁾
Weighing capacity	-	623i-1x ¹⁾ 620	423i-1x¹⁾ 420	323i-1x ¹⁾ 320
Weighing capacity Readability	g	623i-1x¹⁾ 620 0.001	423i-1x¹⁾ 420 0.001	323i-1x ¹⁾ 320 0.001
Weighing capacity Readability Tare range (subtractive) Repeatability	g g	623i-1x¹⁾ 620 0.001 620	423i-1x¹⁾ 420 0.001 420	323i-1x ¹⁾ 320 0.001 320
Weighing capacity Readability Tare range (subtractive) Repeatability (standard deviation)	g g < ± g	623i-1x ¹⁾ 620 0.001 620 0.001	423i-1x ¹⁾ 420 0.001 420 0.001	323i-1x ¹⁾ 320 0.001 320 0.001
Weighing capacity Readability Tare range (subtractive) Repeatability (standard deviation) Linearity deviation	g g < ± g < ± g	623i-1x ¹⁾ 620 0.001 620 0.001 0.001	423i-1x ¹⁾ 420 0.001 420 0.001 0.001 0.001	323i-1x ¹⁾ 320 0.001 320 0.001 0.001 0.002
Weighing capacity Readability Tare range (subtractive) Repeatability (standard deviation) Linearity deviation Typical stabilization time Sensitivity drift within	g g < ± g < ± g s < ± ppm/K	623i-1x ¹⁾ 620 0.001 620 0.001 0.002 1.0 3 By selection o	423i-1x¹⁾ 420 0.001 420 0.001 0.002 1.0 3 f 1 of 4 optimiz	323i-1x ¹⁾ 320 0.001 320 0.001 0.002 1.1 3
Weighing capacity Readability Tare range (subtractive) Repeatability (standard deviation) Linearity deviation Typical stabilization time Sensitivity drift within +10°C +30°C	g g < ± g < ± g s < ± ppm/K	623i-1x ¹⁾ 620 0.001 620 0.001 0.002 1.0 3 By selection o	423i-1x¹⁾ 420 0.001 420 0.001 0.002 1.0 3 f 1 of 4 optimiz	323i-1x ¹⁾ 320 0.001 320 0.001 0.002 1.1 3 ed filter levels;
Weighing capacity Readability Tare range (subtractive) Repeatability (standard deviation) Linearity deviation Typical stabilization time Sensitivity drift within +10°C +30°C Adaptation to ambient conditions External calibration weight	g g < ± g < ± g s < ± ppm/K	623i-1x ¹⁾ 620 0.001 620 0.001 0.002 1.0 3 By selection o display update	423i-1x¹⁾ 420 0.001 420 0.001 0.002 1.0 3 f 1 of 4 optimiz : 0.1-0.4 (dependent)	323i-1x ¹⁾ 320 0.001 320 0.001 0.002 1.1 3 ed filter levels; nding on the set filter level)
Weighing capacity Readability Tare range (subtractive) Repeatability (standard deviation) Linearity deviation Typical stabilization time Sensitivity drift within +10°C +30°C Adaptation to ambient conditions External calibration weight (of at least accuracy class)	g g < ± g < ± g s < ± ppm/K g	623i-1x ¹⁾ 620 0.001 620 0.001 0.002 1.0 3 By selection o display update 500 (E2)	423i-1x¹⁾ 420 0.001 420 0.001 0.002 1.0 3 f 1 of 4 optimiz : 0.1-0.4 (dependence) 200 (E2)	323i-1x ¹⁾ 320 0.001 320 0.001 0.002 1.1 3 ed filter levels; nding on the set filter level) 200 (E2)
Weighing capacity Readability Tare range (subtractive) Repeatability (standard deviation) Linearity deviation Typical stabilization time Sensitivity drift within +10°C +30°C Adaptation to ambient conditions External calibration weight (of at least accuracy class) Net weight, approx.	g g < ± g < ± g s < ± ppm/K g kg	623i-1x ¹⁾ 620 0.001 620 0.001 0.002 1.0 3 By selection o display update 500 (E2) 3.2 3.6	423i-1x ¹⁾ 420 0.001 420 0.001 0.002 1.0 3 f 1 of 4 optimiz : 0.1-0.4 (deper 200 (E2) 3.2 3.6	323i-1x ¹⁾ 320 0.001 320 0.001 0.002 1.1 3 ed filter levels; iding on the set filter level) 200 (E2) 3.2 3.6
Weighing capacity Readability Tare range (subtractive) Repeatability (standard deviation) Linearity deviation Typical stabilization time Sensitivity drift within +10°C +30°C Adaptation to ambient conditions External calibration weight (of at least accuracy class) Net weight, approx. Weighing pan size	g g < ± g < ± g s < ± ppm/K g kg mm	623i-1x ¹⁾ 620 0.001 620 0.001 0.002 1.0 3 By selection o display update 500 (E2) 3.2 3.6 ∅ 115	423i-1x ¹⁾ 420 0.001 420 0.001 0.002 1.0 3 f 1 of 4 optimiz : 0.1-0.4 (deper 200 (E2) 3.2 3.6 ∅ 115 45	323i-1x ¹⁾ 320 0.001 320 0.001 0.002 1.1 3 ed filter levels; nding on the set filter level) 200 (E2) 3.2 3.6 Ø 115

¹⁾ Possible terms for country-specific models:
 x = S: Standard scales without country-specific additions
 x = SUS: Standard scales with country-specific additions for USA
 * Upper edge of the weighing pan to the lower edge of the upper draft shield panel

Modele: Entris		153-1x ¹⁾ 153i-1x ¹⁾		822-1x ¹⁾ 822i-1x ¹⁾	
Weighing capacity	g	150		820	
Readability	g	0.001		0.01	
Tare range (subtractive)	g	150		820	
Repeatability (standard deviation)	< ± g	0.001		0.01	
Linearity deviation	< ± g	0.002		0.03	
Typical stabilization time	S	1.3		1.5	
Sensitivity drift within +10°C +30°C	< ± ppm/K	3		4	
Adaptation to ambient conditions				mized filter lev epends on filte	vels; er level selected)
External calibration weight (of at least accuracy class)	g	100 (E2)		500 (F1)	
Net weight, approx.	kg	2.6 3.0		2.0 2.6	
Weighing pan size	mm	Ø 115		Ø 150	
Weighing chamber height*	mm	45		-	
Dimensions ($W \times D \times H$)	mm	$230 \times 303 \times 10^{-1}$	36	$230 \times 303 \times 8$	37
Modele: Entris		6202-1x ¹⁾	4202-1x ¹⁾ 4202i-1x ¹⁾	3202-1x ¹⁾ 3202i-1x ¹⁾	2202-1x ¹⁾ 2202i-1x ¹⁾
		6202i-1x ¹⁾	42021-1X ^{.,}	J2021-1X	LLOLI IX
Weighing capacity	g	62021-1x ¹ /	4,200	3,200	2,200
Weighing capacity Readability	g		-		
	-	6,200	4,200	3,200	2,200
Readability	g	6,200 0.01	4,200 0.01	3,200 0.01	2,200 0.01
Readability Tare range (subtractive) Repeatability	g	6,200 0.01 6,200	4,200 0.01 4,200	3,200 0.01 3,200	2,200 0.01 2,200
Readability Tare range (subtractive) Repeatability (standard deviation)	g g < ± g	6,200 0.01 6,200 0.01	4,200 0.01 4,200 0.01	3,200 0.01 3,200 0.01	2,200 0.01 2,200 0.01
Readability Tare range (subtractive) Repeatability (standard deviation) Linearity deviation	g g < ± g < ± g	6,200 0.01 6,200 0.01 0.03	4,200 0.01 4,200 0.01 0.03	3,200 0.01 3,200 0.01 0.03	2,200 0.01 2,200 0.01 0.03
Readability Tare range (subtractive) Repeatability (standard deviation) Linearity deviation Typical stabilization time Sensitivity drift within +10°C +30°C Adaptation to ambient conditions	g g < ± g < ± g s < ± ppm/K	6,200 0.01 6,200 0.01 0.03 1.5 4 By selection	4,200 0.01 4,200 0.01 0.03 1.5 4 of 1 of 4 optim	3,200 0.01 3,200 0.01 0.03 1.5	2,200 0.01 2,200 0.01 0.03 1.5 4 vels;
Readability Tare range (subtractive) Repeatability (standard deviation) Linearity deviation Typical stabilization time Sensitivity drift within +10°C +30°C Adaptation to ambient conditions selected)	g g < ± g < ± g s < ± ppm/K	6,200 0.01 6,200 0.01 0.03 1.5 4 By selection display upda	4,200 0.01 4,200 0.01 0.03 1.5 4 of 1 of 4 optin te: 0.1–0.4 (definition)	3,200 0.01 3,200 0.01 0.03 1.5 4 mized filter leve epends on filte	2,200 0.01 2,200 0.01 0.03 1.5 4 rels; er level
Readability Tare range (subtractive) Repeatability (standard deviation) Linearity deviation Typical stabilization time Sensitivity drift within +10°C +30°C Adaptation to ambient conditions selected) External calibration weight (of at least accuracy class)	g g < ± g < ± g s < ± ppm/K	6,200 0.01 6,200 0.01 0.03 1.5 4 By selection display upda 5,000 (E2)	4,200 0.01 4,200 0.01 0.03 1.5 4 of 1 of 4 optin te: 0.1–0.4 (do 2,000 (E2)	3,200 0.01 3,200 0.01 0.03 1.5 4 mized filter levepends on filte 2,000 (E2)	2,200 0.01 2,200 0.01 0.03 1.5 4 rels; er level 2,000 (E2)
Readability Tare range (subtractive) Repeatability (standard deviation) Linearity deviation Typical stabilization time Sensitivity drift within +10°C +30°C Adaptation to ambient conditions selected) External calibration weight (of at least accuracy class) Net weight, approx.	g g < ± g < ± g s < ± ppm/K	6,200 0.01 6,200 0.01 0.03 1.5 4 By selection display upda 5,000 (E2) 3.1 3.5	4,200 0.01 4,200 0.01 0.03 1.5 4 of 1 of 4 optin te: 0.1-0.4 (do 2,000 (E2) 3.1 3.5	3,200 0.01 3,200 0.01 0.03 1.5 4 mized filter levepends on filte 2,000 (E2) 3.1 3.5	2,200 0.01 2,200 0.01 0.03 1.5 4 rels; er level 2,000 (E2) 3.1 3.5
Readability Tare range (subtractive) Repeatability (standard deviation) Linearity deviation Typical stabilization time Sensitivity drift within +10°C +30°C Adaptation to ambient conditions selected) External calibration weight (of at least accuracy class)	g g < ± g < ± g s < ± ppm/K	6,200 0.01 6,200 0.01 0.03 1.5 4 By selection display upda 5,000 (E2)	4,200 0.01 4,200 0.01 0.03 1.5 4 of 1 of 4 optin te: 0.1-0.4 (do 2,000 (E2) 3.1 3.5 180×180	3,200 0.01 3,200 0.01 0.03 1.5 4 mized filter levepends on filte 2,000 (E2)	2,200 0.01 2,200 0.01 0.03 1.5 4 rels; er level 2,000 (E2)

¹⁾ Possible terms for country-specific models:
 x = S: Standard scales without country-specific additions
 x = SUS: Standard scales with country-specific additions for USA
 * Upper edge of the weighing pan to the lower edge of the upper draft shield panel

Modele: Entris		8201-1x ¹⁾ 8201i-1x ¹⁾	5201–1x ¹⁾ 5201i–1x ¹⁾	2201-1x ¹⁾ 2201i-1x ¹⁾
Weighing capacity	g	8,200	5,200	2,200
Readability	g	0.1	0.1	0.1
Tare range (subtractive)	g	8,200	5,200	2,200
Repeatability (standard deviation)	< ± g	0.1	0.1	0.1
Linearity deviation	< ± g	0.3	0.3	0.3
Typical stabilization time	S	1.5	1.5	1.5
Sensitivity drift within +10°C +30°C	< ± ppm/K	8	8	8
Adaptation to ambient conditions	5		f 1 of 4 optimiz	
		display update	: 0.1–0.4 (deper	nds on filter level selected)
External calibration weight (of at least accuracy class)	g	5,000 (F1)	5,000 (F1)	2,000 (F2)
Net weight, approx.	kg	2.7 3.5	2.7 3.5	2.7 3.5
Weighing pan size	mm	180×180	180×180	180×180
Dimensions ($W \times D \times H$)	mm	230×303×91		

 $^{1)}$ Possible terms for country-specific models: x = S: Standard scales without country-specific additions x = SUS: Standard scales with country-specific additions for USA

Accessories


External calibration weights

Accuracy class	Weight in grams	Order No.
E2	200	YCW522-AC-02
E2	100	YCW512-AC-02
E2	50	YCW452-AC-02
F1	500	YCW553-AC-02
F1	200	YCW523-AC-02
F1	200	YCW523-AC-02
F1	100	YCW513-AC-02
F1	5000	YCW653-AC-02
F1	2000	YCW623-AC-02
F1	2000	YCW623-AC-02
F1	2000	YCW623-AC-02
F2	500	YCW554-AC-02
F2	5000	YCW654-AC-02
F2	5000	YCW654-AC-02
F2	2000	YCW624-AC-02
	E2 E2 E2 F1 F1 F1 F1 F1 F1 F1 F1 F1 F1 F1 F2 F2 F2 F2	E2 200 E2 100 E2 50 F1 500 F1 200 F1 200 F1 200 F1 200 F1 200 F1 2000 F1 2000 F1 2000 F1 2000 F1 2000 F1 2000 F2 500 F2 5000

Item	Order No.	
Data printer for reports with date, time, statistics evaluation, item counter functions and LCD display	YDP20-0CE	
Additional display, reflective (for connection to data interface port)	YRD03Z	
External rechargeable battery pack	YRB11Z	
With battery-level indicator (LED); can be recharged using the balance's AC adapter (charge time for completely discharged battery pack: 15 hours); see section "Technical Data" for operating time. To recharge the battery pack: Unplug the AC adapter from the balance and plug it into the battery pack		
Density determination kit, for Entris 224, Entris 124, Entris 64	YDK03	
Data cable		
RS232 25-pin (m) USB type A, length approx. 1.8 m	YCC01-USBM2	
RS232 25-pin (m) 25-pin (f), length approx. 1.5 m	7357312	
RS232 25-pin (m) 9-pin (f), length approx. 2.0 m	7357314	
RS232 25-pin (m) 9-pin (f), length approx. 0.5 m	6965619	

Item	Order No.
lonizing blower for eliminating static electricity	
220 V	YIB01-0DR
120 V	YIB01-0UR
Stat-pen, anti-static device for neutralizing static charges and samples (100 V to 230 V, 50/60 Hz)	YSTP01
Weighing table	
made from wood with natural stone	YWT09
made from natural stone, with vibration dampening	YWT03
Wall console	YWT04
Protective cover	
for models with rectangular weighing pan	6960ED01
for models with round weighing pan (\varnothing 150 mm)	6960ED02
Dust cover for models with sliding door draft shields	6960BP08
Weighing pan	
1000 ml, weight ~240 g, \varnothing 186 mm, h= 77 mm, stainless steel	641211
500 ml, weight ~113 g, \varnothing 151 mm, h= 60 mm, stainless steel	641212
270 ml, weight ~62 g, \varnothing 137 mm, h= 22 mm, stainless steel	YWP03G
350 ml, weight ~75 g, \varnothing 180 mm, h= 22 mm, stainless steel	YWP04G
85 ml, weight ~11 g, \emptyset 83 mm, h= 23 mm, aluminum	YWP06G
180 ml, weight ~32 g, \varnothing 90 mm, h= 48 mm, aluminum	YWP05G

	EG /EII Konformitätsarklär	1100
CE	EG-/EU-Konformitätserklär EC / EU Declaration of Conform	mity
lersteller Manufacturer	Sartorius Lab Instruments GmbH & Co. KG 37070 Goettingen, Germany	
	erklärt in alleiniger Verantwortung, dass das Betriebsm declares under sole responsibility that the equipment	ittel
ieräteart Device type	Elektronische Laborwaage Electronically laboratory balance	
aureihe ype series	ENTRISx-1S, ENTRISxI-1S x = 64, 124, 153, 224, 323, 423, 623, 822, 2201, 2202,	3202, 4202, 5201, 6202, 8201
	in der von uns in Verkehr gebrachten Ausführung aller Europäischen Richtlinien – einschließlich deren zum Ze entspricht und die anwendbaren Anforderungen folge	itpunkt der Erklärung geltenden Änderungen -
	in the form as delivered fulfils all the relevant provisio including any amendments valid at the time this decla requirements of the harmonized European Standards I	ration was signed - and meets the applicable
014/30/EU	Elektromagnetische Verträglichkeit / Electromagnetic o EN 61326-1:2013	compatibility
011/65/EU	Beschränkung der Verwendung bestimmter gefährliche Restriction of the use of certain hazardous substances EN 50581:2012	
014/35/EU	Electrical equipment designed for use within certain w Electrical equipment designed for use within certain w EN 61010-1:2010	
	Statt 2014/35/EU für / instead of 2014/35/EU for ENT	RISxI-1S:
006/42/EG 006/42/EC	Maschinen Machines	
	EN ISO 12100:2010, EN 61010-1:2010	
	Die Person, die bevollmächtigt ist, die technischen Unt The person authorised to compile the technical file:	erlagen zusammenzustellen: Sartorius Lab Instruments GmbH & Co. KG International Certification Management 37070 Goettingen, Germany
	Jahreszahl der CE-Kennzeichenvergabe / Year of the C	E mark assignment: 16
	Sartorius Lab Instruments GmbH & Co. KG Goettingen, 2016-04-20	
	i.v. P. OS_fille i.	V. Hu A
		er Klausgrete International Certification Management
	Diese Erklärung bescheinigt die Übereinstimmung mit den ge Zusicherung von Eigenschaften. Bei einer mit uns nicht abge Erklärung ihre Gültigkeit. Die Sicherheitshinweise der zugehö	stimmten Änderung des Produktes verliert diese
	This declaration certifies conformity with the above mention product attributes. Unauthorised product modifications mak in the associated product documentation must be observed.	





Sartorius Lab Instruments GmbH & Co. KG Otto-Brenner-Strasse 20 37079 Goettingen, Germany

Phone: +49.551.308.0 www.sartorius.com

The information and figures contained in these instructions correspond to the version date specified below.

Sartorius reserves the right to make changes to the technology, features, specifications and design of the equipment without notice. Masculine or feminine forms are used to facilitate legibility in these instructions and always simultaneously denote the other gender as well.

Copyright notice:

This instruction manual, including all of its components, is protected by copyright. Any use beyond the limits of the copyright law is not permitted without our approval. This applies in particular to reprinting, translation and editing irrespective of the type of media used.

© Sartorius Germany

Last updated: 10 | 2018